IMPORTANT

WordPerfect for the Apple IIGs requires ROM version 2.0. If you have ROM version 2.0, "Version 01" appears at the bottom of your computer screen when you turn on your computer, and WordPerfect boots and runs correctly. If you get a "MISSING OR INCOMPATIBLE TOOL—0110" error, you probably need the new ROM.

To further help you check your IIGs, you need to look at the computer's serial number. If the first three digits of the serial number are between 705 and 724, you need the new ROM. If the first three digits of the serial number are less than 705, you need both a new ROM and a new VGC (Video Graphics Controller). While WordPerfect does not require the VGC directly, the VGC will eliminate certain color flickering problems.

The new ROM is available free of charge from your nearest authorized Apple dealer.